

# EASTERN ELECTRIC

APPARATUS  
REPAIR  
COMPANY, INC.

10831 East Marginal Way, South  
Seattle, WA 98168

(206) 767-9506  
(206) 767-0556 Fax

LDWSF  
12.3.376.1  
VII

RECEIVED  
SEP 24 1993

September 21, 1993


Paccar Inc  
1400 N 4th St  
Renton, WA 98055

Attention: Claus Hackenburger

This letter is to certify that the 12 PCB Ballasts delivered to  
Eastern Electric Apparatus Service Plant, Seattle, WA on 5-21-93  
were disposed of according to 40 CFR Part 761.60 (b) (2) (iii) (A).

Attached are copies of the Hazardous Waste Manifest, Ticket Number  
00157940, and the Certificate of Destruction in which your ballasts  
were included.

Should you have any questions, please feel free to call.



EASTERN ELECTRIC CORPORATION

*Called - he will call back  
9-27-93*

*Letter, these are the Seaboard Ballasts.*

*9-28-93*

ACCOUNTS

SEP 23 1993

PAYABLE

088

USEPA SF



1358804



TEXAS WATER COMMISSION  
P.O. Box 13087, Capitol Station  
Austin, Texas 78711-3087



Please print or type. (Form designed for use on elite (12-pitch) typewriter.)

Form approved. OMB No. 2050-0039, expires 09-30-91

UNIFORM HAZARDOUS WASTE MANIFEST		1. Generator's US EPA ID No. WAD98073846200008	Manifest Document No.	2. Page 1 of 2	Information in the shaded areas is not required by Federal law.		
3. Generator's Name and Mailing Address EASTERN ELECTRIC 10831 E. MARGINAL WAY S. SEATTLE, WA 98168				A. State Manifest Document Number NO 00157940			
4. Generator's Phone (206) 767-9506 ATTN: LARRY ROBINSON				B. State Generator's ID 99953			
5. Transporter 1 Company Name DART TRUCKING CO., INC.				C. State Transporter's ID 40613			
6. US EPA ID Number KHDO09865825				D. Transporter's Phone (206) 541-8206			
7. Transporter 2 Company Name				E. State Transporter's ID			
8. US EPA ID Number				F. Transporter's Phone			
9. Designated Facility Name and Site Address ROLLINS ENVIRONMENTAL SER. 3027 BATTLEGROUND DEER PARK, TX 77536				G. State Facility's ID HW 50089			
10. US EPA ID Number TXD055141378				H. Facility's Phone (713) 930-2300			
11A. HM	11. US DOT Description (including Proper Shipping Name, Hazard Class, and ID Number)		12. Containers No.	Type	13. Total Quantity	14. Unit Wt/Vol	15. Waste No.
	a. R.O. HAZARDOUS SUBSTANCE, SOLID, N.O.S., ORM-E, NA 9188 (POLYCHLORINATED BIPHENYLS)		002	CM	1793	K	173880
	b. R.O. HAZARDOUS SUBSTANCE, SOLID, N.O.S., ORM-E, NA 9188 (POLYCHLORINATED BIPHENYLS)		001	DM	125	K	173880
	c.						
	d.						
J. Additional Descriptions for Materials Listed Above				K. Handling Codes for Wastes Listed Above			
a. BINS OF PCB CAPACITORS				EMERGENCY RESPONSE			
b. DRUM OF PCB CAPACITORS				CHEMTREC			
HO-11533-39				(800) 424-9300			
15. Special Handling Instructions and Additional Information (SEE CONTINUATION PAGE)							
16. GENERATOR'S CERTIFICATION: I hereby declare that the contents of this consignment are fully and accurately described above by proper shipping name and are classified, packed, marked, and labeled, and are in all respects in proper condition for transport by highway according to applicable international and national government regulations, including applicable state regulations. If I am a large quantity generator, I certify that I have a program in place to reduce the volume and toxicity of waste generated to the degree I have determined to be economically practicable and that I have selected the practicable method of treatment, storage, or disposal currently available to me which minimizes the present and future threat to human health and the environment; OR, if I am a small quantity generator, I have made a good faith effort to minimize my waste generation and select the best waste management method that is available to me and that I can afford.							
Printed/Typed Name J.W. SHEAROUSE				Signature J.W. Shearouse		Month Day Year 8/31/93	
17. Transporter 1 Acknowledgement of Receipt of Materials						Date	
Printed/Typed Name James Bull				Signature James Bull		Month Day Year 08/31/93	
18. Transporter 2 Acknowledgement of Receipt of Materials						Date	
Printed/Typed Name				Signature ACCOUNTS		Month Day Year	
19. Discrepancy Indication Space SEP 23 1993 PAYABLE							
20. Facility Owner or Operator: Certification of receipt of hazardous materials covered by this manifest except as noted in Item 19.							
Printed/Typed Name K. SCHAFER				Signature K. Schaffer		Month Day Year 9/9/93	

PROGRAM-ID: PTR1722C

ROLLINS ENVIRONMENTAL SERVICES (TX) INC

RUN DATE : 9/15/93

CERTIFICATE OF DISPOSAL

RUN TIME : 5:19 PM

PAGE: 1

\*\*\*\*\*

Certificate of Disposal

Stream

Order

Manifest Received Final

Name and Address

Number

Number

Number

Date

Disposal

\*\*\*\*\*

011553

159577

TX00157940 09/09/93 09/10/93


EASTERN ELECTRIC

10831 E MARGINAL WAY

SEATTLE

WA 98168

Attn: LARRY ROBINSON



Inventory	Customer's Unique	CONTAINER	Prod SHP	Disposal
Cntrl Nbr	Serial Number	Type	Code	TO Mthd Date
002901777	772	BIN	39	I 09/10/93
002901778	671	BIN	39	I 09/10/93
002901780	AP-1	55SD	39	I 09/10/93
Total Containers :		3		

ACCOUNTS  
SEP 23 1993  
PAYABLE

PROGRAM-ID: PTR1722C

ROLLINS ENVIRONMENTAL SERVICES (TX) INC

RUN DATE : 9/15/93

CERTIFICATE OF DISPOSAL

RUN TIME : 5:19 PM

PAGE: 2

\*\*\*\*\*

This completes the Certificates of Destruction per Manifest Number TX00157940.


\*\*\*\*\*

\* Disposal Methods : \*  
\* 'I' - Waste that was incinerated. \*  
\* 'L' - Waste that was landfilled. \*  
\* Disposal Facility : ROLLINS ENVIRONMENTAL SERVICES (TX) INC \*  
\* PO BOX 609 \*  
\* DEER PARK TX 77536 \*  
\* EPA ID: TXD055141378 \*  
\* \*

\*\*\*\*\*

Under civil and criminal penalties of law for making or submission of false or fraudulent statements or representations (18 U.S.C. 1001 and 15 U.S.C. 2615), I certify that the information contained in or accompanying this document is true, accurate and complete. As to the identified section(s) of this document for which I cannot personally verify truth accuracy, I certify as the company official having supervisory responsibility for the persons who, acting under my direct instructions, made the verification that this information is true, accurate, and complete.

Please call (713) 930-2317 if there are any questions concerning the information on this Certificate of Disposal.

  
Authorized Agent  
ROLLINS ENVIRONMENTAL SERVICES (TX) INC

ACCOUNTS  
SEP 23 1993  
PAYABLE

5792

UNIFORM HAZARDOUS WASTE MANIFEST		1. Generator's US EPA ID No.	Manifest Document No.	2. Page 1 of 1	Information in the shaded areas is not required by Federal law.	
3. Generator's Name and Mailing Address <b>PAC CAR, INC. 1400 N. 4TH ST. RENTON, WA 98055</b>				A. State Manifest Document Number		
4. Generator's Phone (206) 251-7514 ATTN: CLAUD HACKENBERGER				B. State Generator's ID		
5. Transporter 1 Company Name <b>EASTERN ELECTRIC</b>		6. US EPA ID Number <b>WAD980738462</b>		C. State Transporter's ID		
7. Transporter 2 Company Name		8. US EPA ID Number		D. Transporter's Phone (206) 767-9506		
9. Designated Facility Name and Site Address <b>EASTERN ELECTRIC 10831 E. MARGINAL WAY S. SEATTLE, WA 98168</b>		10. US EPA ID Number <b>WAD980738462</b>		E. State Transporter's ID		
				F. Transporter's Phone		
				G. State Facility's ID		
				H. Facility's Phone (206) 767-9506		
11. US DOT Description (Including Proper Shipping Name, Hazard Class, and ID Number)				12. Containers	13. Total Quantity	14. Unit Wt/Vol
a. <b>R.O., HAZARDOUS SUBSTANCE, SOLID, N.O.S., ORM-E, NA 9188 (POLYCHLORINATED BIPHENYLS)</b>				No. <b>001 DM</b>	<b>30</b>	<b>K</b>
b.						
c.						
d.						
J. Additional Descriptions for Materials Listed Above <b>a. DRUM OF PCB BALLAST</b>				K. Handling Codes for Wastes Listed Above <b>EMERGENCY RESPONSE CHEMTREC (800) 424-9300</b>		
15. Special Handling Instructions and Additional Information <b>UNIQUE ID NUMBER - PAC-001 OUT OF SERVICE DATE - 5-13-93 PCB WASTE CODE - PCB 1</b>						
16. GENERATOR'S CERTIFICATION: I hereby declare that the contents of this consignment are fully and accurately described above by proper shipping name and are classified, packed, marked, and labeled, and are in all respects in proper condition for transport by highway according to applicable international and national governmental regulations. If I am a large quantity generator, I certify that I have a program in place to reduce the volume and toxicity of waste generated to the degree I have determined to be economically practicable and that I have selected the practicable method of treatment, storage, or disposal currently available to me which minimizes the present and future threat to human health and the environment; OR, if I am a small quantity generator, I have made a good faith effort to minimize my waste generation and select the best waste management method that is available to me and that I can afford.						
Printed/Typed Name <b>JACK DOTTAVIO</b>		Signature <i>Jack Dottavio</i>		Month Day Year <b>05/21/93</b>		
17. Transporter 1 Acknowledgement of Receipt of Materials		Printed/Typed Name <b>LARRY ROBINSON</b>		Signature <i>Larry Robinson</i>		Month Day Year <b>05/21/93</b>
18. Transporter 2 Acknowledgement of Receipt of Materials		Printed/Typed Name <b>J</b>		Signature <i>J</i>		Month Day Year <b>05/21/93</b>
19. Discrepancy Indication Space <b>RECEIVED MAY 24 1993</b>						
20. Facility Owner or Operator: Certification of receipt of hazardous materials covered by this manifest except as noted in Item 19.						
Printed/Typed Name <b>LARRY ROBINSON</b>		Signature <i>Larry Robinson</i>		Month Day Year <b>05/21/93</b>		

ORIGINAL - RETURN TO GENERATOR

# UNIFORM HAZARDOUS WASTE MANIFEST AND INSTRUCTIONS EPA FORM 8700-22

U.S. EPA Form 8700-22

Read all instructions before completing this form.

This form has been designed for use on a 12-pitch (elite) typewriter; a firm point pen may also be used — press down hard.

Federal regulations require generators and transporters of hazardous waste and owners or operators of hazardous waste treatment, storage, and disposal facilities to use this form (8700-22) and, if necessary, the continuation sheet (Form 8700-22A) for both inter- and intrastate transportation.

Federal regulations also require generators and transporters of hazardous waste and owners or operators of hazardous waste treatment, storage and disposal facilities to complete the following information:

## GENERATORS

### Item 1. Generator's U.S. EPA ID Number — Manifest Document Number

Enter the generator's U.S. EPA twelve digit identification number and the unique five digit number assigned to this Manifest (e.g., 00001) by the generator.

### Item 2. Page 1 of —

Enter the total number of pages used to complete this Manifest, i.e., the first page (EPA Form 8700-22) plus the number of Continuation Sheets (EPA Form 8700-22A), if any.

### Item 3. Generator's Name and Mailing Address

Enter the name and mailing address of the generator. The address should be the location that will manage the returned Manifest forms.

### Item 4. Generator's Phone Number

Enter a telephone number where an authorized agent of the generator may be reached in the event of an emergency.

### Item 5. Transporter 1 Company Name

Enter the company name of the first transporter who will transport the waste.

### Item 6. U.S. EPA ID Number

Enter the U.S. EPA twelve digit identification number of the first transporter identified in item 5.

### Item 7. Transporter 2 Company Name

If applicable, enter the company name of the second transporter who will transport the waste. If more than two transporters are used to transport the waste, use a Continuation Sheet(s) (EPA Form 8700-22A) and list the transporters in the order they will be transporting the waste.

### Item 8. U.S. EPA ID Number

If applicable, enter the U.S. EPA twelve digit identification number of the second transporter identified in item 7.

**Note.**—If more than two transporters are used, enter each additional transporter's company name and U.S. EPA twelve digit identification number in items 24-27 on the Continuation Sheet (EPA Form 8700-22A). Each Continuation Sheet has space to record two additional transporters. Every transporter used between the generator and the designated facility must be listed.

### Item 9. Designated Facility Name and Site Address

Enter the company name and site address of the facility designated to receive the waste listed on this Manifest. The address must be the site address, which may differ from the company mailing address.

### Item 10. U.S. EPA ID Number

Enter the U.S. EPA twelve digit identification number of the designated facility identified in item 9.

### Item 11. U.S. DOT Description (Including Proper Shipping Name, Hazard Class, and ID Number (UN/NA))

Enter the U.S. DOT Proper Shipping Name, Hazard Class, and ID Number (UN/NA) for each waste as identified in 49 CFR 171 through 177.

**Note.**—If additional space is needed for waste descriptions, enter these additional descriptions in item 28 on the Continuation Sheet (EPA Form 8700-22A).

### Item 12. Containers (No. and Type)

Enter the number of containers for each waste and the appropriate abbreviation from Table I (below) for the type of container.

Table I — Types of Containers

DM = Metal drums, barrels, kegs	CY = Cylinders
DW = Wooden drums, barrels, kegs	CM = Metal boxes, cartons, cases (including roll-offs)
DF = Fiberboard or plastic drums, barrels, kegs	CW = Wooden boxes, cartons, cases
TP = Tanks portable	CF = Fiber or plastic boxes, cartons, cases
TT = Cargo tanks (tank trucks)	BA = Burlap, cloth, paper or plastic bags
TC = Tank cars	
DT = Dump truck	

### Item 13. Total Quantity

Enter the total quantity of waste described on each line.

### Item 14. Unit (Wt./Vol.)

Enter the appropriate abbreviation from Table II (below) for the unit of measure.

Table II — Units of Measure

G = Gallons (liquids only)	L = Liters (liquids only)
P = Pounds	K = Kilograms
T = Tons (2000 lbs)	M = Metric tons (1000 kg)
Y = Cubic yards	

### Item 15. Special Handling Instructions and Additional Information

Generators may use this space to indicate special transportation, treatment, storage, or disposal information or Bill of Lading information. States may not require additional, new, or different information in this space. For international shipments, generators must enter in this space the point of departure (City and State) for those shipments destined for treatment, storage, or disposal outside the jurisdiction of the United States.

For international shipments, generators must enter in this space the point of departure (City and State) for those shipments destined for treatment, storage, or disposal outside the jurisdiction of the United States.

### Item 16. Generator's Certification

The generator must read, sign (by hand), and date the certification statement. If a mode other than highway is used, the word "highway" should be lined out and the appropriate mode (rail, water, or air) inserted in the space below. If another mode in addition to the highway mode is used, enter the appropriate additional mode (e.g., and rail) in the space below.

Primary exporters shipping hazardous wastes to a facility located outside of the United States must add to the end of the first sentence of the certification the following words and conform to the terms of the EPA Acknowledgment of Consent to the shipment.

In signing the waste minimization certification statement, those generators who have not been exempted by statute or regulation from the duty to make a waste minimization certification under section 3002(b) of RCRA are also certifying that they have complied with the waste minimization requirements.

Generators may preprint the words "On behalf of" in the signature block or may hand write this statement on the signature block prior to signing the generator certifications.

**Note.**—All of the above information except the handwritten signature required in item 16 may be preprinted.

## TRANSPORTERS

### Item 17. Transporter 1 Acknowledgement of Receipt of Materials

Enter the name of the person accepting the waste on behalf of the first transporter. That person must acknowledge acceptance of the waste described on the Manifest by signing and entering the date of receipt.

### Item 18. Transporter 2 Acknowledgement of Receipt of Materials

Enter, if applicable, the name of the person accepting the waste on behalf of the second transporter. That person must acknowledge acceptance of the waste described on the Manifest by signing and entering the date of receipt.

**Note.**—International Shipments — Transporter Responsibilities.

**Exports.**—Transporters must sign and enter the date the waste left the United States in item 15 of Form 8700-22.

**Imports.**—Shipments of hazardous waste regulated by RCRA and transported into the United States from another country must upon entry be accompanied by the U.S. EPA Uniform Hazardous Waste Manifest. Transporters who transport hazardous waste into the United States from another country are responsible for completing the Manifest (40 CFR 263.10(c)(1)).

## OWNERS AND OPERATORS OF TREATMENT, STORAGE, OR DISPOSAL FACILITIES

### Item 19. Discrepancy Indication Space

The authorized representative of the designated (or alternate) facility's owner or operator must note in this space any significant discrepancy between the waste described on the Manifest and the waste actually received at the facility.

Owners and operators of facilities located in unauthorized States (i.e., the U.S. EPA administers the hazardous waste management program) who cannot resolve significant discrepancies within 15 days of receiving the waste must submit to their Regional Administrator (see list below) a letter with a copy of the Manifest at issue describing the discrepancy and attempts to reconcile it (40 CFR 264.72 and 265.72).

Owners and operators of facilities located in authorized States (i.e., those States that have received authorization from the U.S. EPA to administer the hazardous waste program) should contact their State agency for information on State discrepancy report requirements.

### EPA Regional Administrators

Regional Administrator, U.S. EPA Region I, F. Kennedy Fed. Bldg., Boston, MA 02203

Regional Administrator, U.S. EPA Region II, 26 Federal Plaza, New York, NY 10278

Regional Administrator, U.S. EPA Region III, 6th and Walnut Sts., Philadelphia, PA 19106

Regional Administrator, U.S. EPA Region IV, 345 Courtland St., NE, Atlanta, GA 30365

Regional Administrator, U.S. EPA Region V, 230 S. Dearborn St., Chicago, IL 60604

Regional Administrator, U.S. EPA Region VI, 1201 Elm Street, Dallas, TX 75270

Regional Administrator, U.S. EPA Region VII, 324 East 11th Street, Kansas City, MO 64106

Regional Administrator, U.S. EPA Region VIII, 1860 Lincoln Street, Denver, CO 80295

Regional Administrator, U.S. EPA Region IX, 115 Fremont Street, San Francisco, CA 94105

Regional Administrator, U.S. EPA Region X, 1200 Sixth Avenue, Seattle, WA 98101

### Item 20. Facility Owner or Operator: Certification of Receipt of Hazardous Materials Covered by This Manifest Except as Noted in Item 19

Print or type the name of the person accepting the waste on behalf of the owner or operator of the facility. That person must acknowledge acceptance of the waste described on the Manifest by signing and entering the date of receipt.

Items A-K are not required by Federal regulations for intra- or interstate transportation. However, States may require generators and owners or operators of treatment, storage, or disposal facilities to complete some or all of items A-K as part of State manifest reporting requirements. Generators and owners and operators of treatment, storage, or disposal facilities are advised to contact State officials for guidance on completing the shaded areas of the Manifest.